




Please read these instructions carefully before installing or using the CAT EYE ASTRALE 8.

Please don't throw away this manual, Keep the manual at a place easily accessible.

Installation of the Computer on Your Bike

The computer comeswith the following parts.



- Bracket
- Cord
- Speed Sensor
- (short cord)
- Cadence Sensor (long cord)
- Sensor Rubber Pad Wheel Magnet Cadence Magnet




Mount the wheel magnet and speed sensor

8 Bracket Rubber Pad

Nylon Ties (12)

- Mount the wheel magnet 6 on a spoke of the front wheel so the surface of the magnet will face the sensor
- Secure the speed sensor 3 on the front fork with the larger nylon ties 9




Mount the cadence magnet and cadence sensor.

- Mount the cadence magnet **7** on the crank arm so that it faces the sensor.
- Secure the cadence sensor 4 on the left chain stay with the nylon ties 9




Important Note


Mount the magnets $\mathbf{6}$ ($\mathbf{7}$) and the sensors $\mathbf{3}$ ($\mathbf{4}$) on the appropriate positions so that the center of each magnet (a) may align with the the marked line on the sensor when the front wheel (or the crank arm) is rotated.



Important Note

Adjust the position of each sensor so they are within 5mm of the 6 (1) magnet. Secure the nylon ties.







Note

- Pay attention to the road or trail! Do not be distracted by the computer.
- Be sure to securely mount the magnet, the sensor, and the bracket on your bicycle. Periodically check to insure they are mounted securely and the screws are not loosen.
- Keep batteries out of reach of small children. Dispose of batteries according to local regulations.

Important

- Avoid unnecessary prolonged exposure to the sun. Never attempt to disassemble the computer head. Don't use thinner, benzene or alcohol to wipe the surface of the
- computer. They may damage the surface of computer.


Mount The Bracket

Secure the cord on the frame or the fork with the nylon ties

and coil it around the brake cable to lead to the handle bar.

Put the rubber pad 8 on the bracket 1 and secure the bracket on the handle bar with the screw. Slide the computer into the bracket until you hear the click sound. The contact points are automatically closed. When you need to remove the computer, slide forward the computer with the lever pushed simultaneously.

Note Allow enough wire clearance in the area marked with \Rightarrow to insure you can turn the handlebars all the way from side to side without pulling the wire



Basic Functions Test

Spin the front wheel to see if Speed is reading properly. Push the mode button until Cadence (Cdc) is in the sub-display. Spin the crank arm backwards to test if Cadence is reading properly

When the computer does not indicate the speed/cadence, check the position of the magnet and the sensor.






You need to know the

tire circumference (L mm) beforehand.

Rotate the crank arm

Computer Set-up

(For first use or after replacing the battery)



You can refer to the Tire size

AC Button

L(mm)

1020 1055

guide chart to roughly know the tire circum-

> 14 x 1.50 14 x 1.75 16 x 1.75 16 x 1.75 16 x 1.75 18 x 1.50 18 x 1 75 20 x 1-3/8 22 x 1-3/8

All Clear

MODE Button

Push the AC button on the backside.

Push the AC button when using this system for the first time and every time the battery is replaced.

Measurement Selection

START/STOP Button

Select the measurement unit, kilometer or mile, by pushing the MODE button. And fix it by pushing the SET button.






Set The Tire Circumference

Set the tire circumference in mm.

Note Refer to the chart shown on the right. Setting is fixed and completed by pushing the SET button.



Preparation Complete. (the screen will show the time measurement in this state)

* The auto mode is ON in this state

1340 1350 1515 1615 1770 22 x 1-1/2 24 x 1 24 x 3/4 Tubu 1785 24 x 1-1/8 24 x 1-1/4 1795 1905 1890 1925 24 x 2.00 24 x 2.125 1965 26 x 7/8 1920 26 x 1(59) 26 x 1(65) 26 x 1.25 26 x 1-1/8 1913 1952 1953 1970 26 x 1-3/8 26 x 1-1/2 26 x 1.40 2068 2100 2005 26 x 1.50 2010 2050 26 x 2.00 2055 26 x 2.10 2068 26 x 2 125 2070 26 x 2.35 26 x 3.00 27 x 1 2155 27 x 1-1/8 27 x 1-1/4 27 x 1-3/8 2161 650 x 35A 2090 650 x 38A 2125 650 x 38B 700 x 18C 2070 700 x 19C 2080 700 x 20C 2086 **700 x 23C** 700 x 25C **2096** 2105 700 x 28C 700 x 30C 2136 2170 700 x 30C 700 x 32C 700C Tubula 700 x 35C 700 x 38C 2180

Tire size is usually shown on the sidewall of tires.

Computer Operations

Selection of the data-display mode (bottom of the screen)

Press the Mode button to navigate to each of the sub-displays listed on the right. Press and hold the mode button for two seconds in any mode to display the Clock Time.

Start or Stop of Measurements

The computer can be programmed to run in either MANUAL MODE or AUTO TIME MODE. In Manual Mode you must press the START / STOP button to turn on and off the Timer, which records Distance and Average Speeds. In Auto Time the computer turns the Timer on and off depending on a signal from the

When speed is detected by the computer and the Timer is running, the km/h or mph will flash. Speed will appear on the computer screen and the Odometer will record, regardless if the Timer is running or not.

Auto Time Mode (Automatic Measurement)

When the icon AT is lit, the measurements are automatically done. This is called auto-mode in which the rotation of the wheel is detected to make the measurements start or stop automatically. (When the icon AT is lit, you cannot start or stop the measurements by pushing the START/STOP button)

Manual Measurements

When you don't see the icon **AT** on the screen, you can start or stop the measurements by pushing the START/STOP button. When you push the button, measurements Elapsed Time, Average Speed and Trip Distance are started, and stopped with the second push of the button.

• How to set ON or OFF the Auto-Mode

Push the SET button while Elapsed Time (Tm) Trip Distance (Dst) or Average Speed (Av) is displayed, then the icon AT is "lit" (ON) or turned OFF.

Resetting Elapsed Time, Trip Distance, Average and Max. Speed

Push the MODE button and the START/STOP button at the same time while the measurement other than Odometer. Elansed time, Maximum Speed, Average Speed and Trip Distance are zeroed. The Odometer cannot be reset.











While Elapsed Time. Trip Distance or Aver age Speed is displayed

(0.00.00) MODE ST/STOP

Computer Functions


Power-Saving Function

When no signal has been received for about 1 hr, the computer switches to the power-saving mode and only displays the Clock. When any button is pushed or the bicycle is riden, the measurement mode comes back

• Selection of The Data-display Mode

In Auto-Mode you can choose between Speed or Cadence to be displayed in the top

Speed is initially selected in the upper display. When the computer is in AT mode, press the START/STOP button. Cadence will now appear in the upper display. Speed will be in the lower display. Switch it back with the same procedure.



Troubleshooting

No display appears

Is the battery dead?

Replace it and do all clear procedure

Strange data appears

Do all clear procedure.

Data of odometer is also erased.

Measurements do not start when the START/STOP button is pushed.

Is the icon ATI ON?

Make the Auto-Mode off to enable the start or stop of the measurements by manual operation of the button

No speed data (cadence) can be measured.

(If the speed data (cadence) is not displayed, have the contact points short-circuited a few times by a metal plate. In the case that this short-circuiting is detected by the computer, the computer is considered normal and the bracket and the sensor possibly have the cause of trouble.)

Is the gap between the sensor and the magnet too big? (should be within 5 mm)

Does the marked line of the sensor align with the center of the magnet?

Adjust the position of the magnet and the sensor.

Make sure that the contact points of the bracket or of the main body are free from dirt. Wipe the contact points clean.

Is the cord not broken? Even if the outside of the cord looks normal, a breakage in the wire can occur. Replace the bracket and sensor set with a new one

Maintenance

• To clean the computer or the attached parts, use diluted neutral detergent on a soft cloth and wipe it off with a dry cloth.

Replacing The Battery

When the display becomes dim, replace the battery.

- Put a lithium battery CR2032 in the computer with the (+) mark facing up.
- · After replacing the battery, do the necessary set-up of the computer in accordance with the "Computer Set-up".





Is the contact points located on

the backside short-circuited in

termittently

Display for Measurements





Specifications

A Lithium Battery (CR2032), Approx:3 yrs. Battery/Its Life : (Approx:1 hr per day usage.)

Control System: ---4-bit 1-chip micro-computer (with a crystal oscillator)

Liquid crystal display Display

No-contact magnetic sensor Sensing System: --Range of tire circumference setting: ----- 10 mm - 2999 mm (Initial value 2096 mm)

Range of Operational Temperature: ----- 0°C - 40°C (32°F - 104°F)

Dimension and Weight(Computer): ----- 38 x 54 x 17.5 mm [1-1/2 x 2-1/8 x 11/16"] / 28 g [1.0 oz]

* The factory-loaded battery life might be shorter than the above-mentioned specification.

* The specifications and design are subject to change without notice.

Limited Warranty

2-Year Warranty: Computer Head Only (excluding the attached parts and deteriorated battery)

If any trouble or damage occurs during normal use, the product computer will be repaired or replaced free of charge. Type your name, address, telephone number or e-mail address, date of purchase and the situation of trouble and send it back together with the product to the closest address below. Transportation charges shall be borne by the customer. After being repaired, the product will be shipped back to the customer

CAT EYE co.,LTD. 2-8-25, Kuwazu, Higashi Sumiyoshi-ku, Osaka 546-0041 Japan

Attn.: CAT EYE Customer Service Section
Service & Research Address for United States Consumers: CAT EYE Service & Research Center

1705 14th St. 115 Boulder, CO 80302

Phone: 303-443-4595 Fax: 303-473-0006

Toll Free: 800-5CATEYE e-mail: service@cateye.com URL: http://www.cateve.com

* Accessory parts are available for the customers as shown below

